Printed
January 25 1982

RFP 3226 UC 70 NUCLEAR WASTE MANAGEMENT TIC-4500 (Rev 69)

REMOVAL OF PLUTONIUM-CONTAMINATED SOIL FROM THE 903 LIP AREA DURING 1976 AND 1978

C. J Barker

R. D Howerton Editor
L M Morales Compositor

SUBJECT DESCRIPTORS

Contaminated Soil
Plutonium in Soil
Soil Removal
1 5224
Facher C J.
Lup Greek

ROCKWELL INTERNATIONAL ENERGY SYSTEMS GROUP ROCKY FLATS PLANT P.O. SOX 484 GOLDEN COLORADO 80401

ADMIN RECORD

Prepared under Contract DE-AC04-76DPO3633
for the
Albuquerque Operations Office
U.S. Department of Energy

The state of

REVIEWED FOR CLASSIFICATION

REVIEWED FOR CLASSIFICATION/LICH

BY S. L. CUNNINGHAM

7/3/10

A-DU02-000009

CONTENTS

Abstract	1
Introduction	1
History of the Plutonium-Contaminated Oil Drum Storage Area (903 Area)	1
History of the Plutonium-Contaminated 903 Lip Area	2
Soil Removal Project - Summer 1976	4
Soil Removal Project - Summer 1978	4
Conclusions	7

REMOVAL OF PLUTONIUM-CONTAMINATED SOIL FROM THE

903 LIP AREA DURING 1976 AND 1978

C J Barker

ABSTRACT

This report describes the removal of plutonium contaminated soil from the 903 Lip Area at the Rocky Flats Plant Golden Colorado. The report includes the history of the contamination development work associated with planning soil removal descriptions of the work performed using two different methods of soil removal, and data indicating that the soil removal was conducted with no adverse impact on the environment.

ANTRODUCTION

The Rocky Flats Plant is a Department of Energy (DOE) facility involved in the fabrication of nuclear weapons components. The Plant established in 1951 is operated for the DOE by the Energy Systems Group of Rockwell International

An extensive environmental control and surveillance program is conducted at the Plant by the Environmental Sciences branch of the Health, Safety and Environment department. The program is designed to ensure that safeguards at the Plant keep the release of radioactive and toxic materials within the DOE concept of "As Low As Practicable (ALAP)"

As part of the effort to meet the ALAP criteria the Rocky Flats Plant has an ongoing program designed to clean up previously contaminated areas at the site. An example of the program occurred during the summers of 1976 and 1978 when plutonium-con taminated soil was removed from an area designated as the 903 Lip Area. This area is adjacent to a ortion of the Plant formerly known as the Oil Jrum Storage Area These two areas are shown in Figure 1

a addition the bearing

This report documents the efforts involved in planning and performing the cleanup with no adverse environmental impact

HISTORY OF THE
PLUTONIUM-CONTAMINATED
OIL DRUM STORAGE AREA (903 AREA)

From the beginning of plutonium operations at the Rocky Flats Plant in May 1953 organic liquids contaminated with plutonium have been generated in various manufacturing operations. Processes for recovering plutonium from these liquids (mainly lathe coolant oils) were not developed until 1967

In July 1958 an outside oil drum storage field was established and during subsequent years, drums containing plutonium-contaminated machining oils were continually added to the storage area. Drum leakage was first discovered in the storage area in 1959 From that time on to minimize corrosion a rust inhibitor (ethanolamine) was added to all drums prior to storage. Despite that preventative action evidence of drum deterioration and soil contamination was found in 1964 Work was accelerated toward developing processes and equipment that would recover plutonium contained in the drum-stored oils. In January 1967, removal of the drums from the storage area began, and by June 1968 the last drum had been removed to a processing facility In 1969 fill material and soil sterilant were applied to the drum storage field and by November of that year an asphalt contain ment cover (shown in Figure 1) was completed * It is believed that those work activities plus high

This area is often referred to as the (asphalt) pad area.




FIGURE 1 Soil Removal Ar as

18263 20

winds predominately from the northwest contributed to the spread of radioactivity to adjacent arc is. One of these areas is called the 903 Lip. Area which is immediately southeast of the drum storage field. As shown in Figure 2 measured concentrations of total long lived alpha activity at Air Sampler S 7 (east of the drum storage field) increased during the time of these activities.

It is estimated that the amount of plutonium de out dan the drum storage area was 6.3 curies that total an estimated one arise of plutonium

A h 1 se 1 t t 15 plr57 w d 1 d 5 mpl 5 8 was redistributed beyond the pad area and of that one cure 0.56 cure is believed to have been deposited in the 903 Lip Area

HISTORY OF THE PLUTONIUM-CONTAMINATED 903 LIP AREA

Surveys at the time of the drum removal project and subsequent annual soil sampling showed a maximum plutonium concentration of 5 680 1/m/k (-558 p (1/k) in the top 5 cm of soil in the 303 lip \r + \ln \ln \ln 197 \r \rangle \text{a aerial radiological} \r \text{mint rink ups s (\lambda RMS) by FC&G Inc Las \rangle \




FIGURE 2. Total Long-Lived Alpha Concentrations From Air Sampler S-7 East of the Drum Storage Area. Sampler S-7 was formerly identified as Sampler S-8

Personnel from the ERDA Health and Safety
Laboratory (now DOE Environmental Measurements Laboratory) conducted a soil sampling
effort and direct reading surveys (using a FIDLER,
which is a field instrument for detecting low
energy radiation). These two simultaneous surveys
confirmed the ARMS indications.

In February 1974 a public briefing was held at the Rocky Flats Plant for the Governor of the State of Colorado and other State officials. During that briefing and in subsequent press releases, ERDA (now DOE) made a commitment to further stabilize or remove the contaminated soil in the 903 Lip Area.

A practice soil excavation to help develop an effective removal technique was performed on May 5 1975 in an uncontaminated area about 350 m northwest of the contaminated area

On May 13 and 14 1975 personnel from the Health and Safety Laboratory with the aid of

Rocky Flats personnel, excavated two trenches in the contaminated area. The techniques used were those developed in the practice excavation. Eight 55-gal drums of contaminated soil were removed from the two trenches Subsequent analysis of high-volume air samples taken during the excavation process indicated a plutonium concentration of 0 00258 pCI/m³ This value was fairly consistent with the range of annual averages for routine air samplers located in the same general vicinity. At that time, those samplers ranged from concentrations of 0 001 to 0 003 pCI/m³ The DOE Radioactivity Concentration Guide (RCG) for soluble plutonium in ambient air accessible to incidentally exposed individuals is 0.06 pCi/m³ It was concluded that the excavation work in the contaminated 903 Lip Area had created no hazardous conditions for either industrial workers or the offsite population. Also no adverse environmental impact was created Based on these conclusions, a plan for removing the plutonium contamination from the entire 903 Lip Area was decided upon and work began in the summer of 1976

***OIL REMOVAL PROJECT - SUMMER 1976**

An Environmental Assessment for removing plutonium-contaminated soil from the 903 Lip Area was distributed on June 1 1976 and soil removal began on June 28. The procedure to be used during soil removal was detailed in the document and was based on the technique used by Health and Safety Laboratory personnel during the trench excavation in May 1975.

All personnel involved in excavation and packaging of the soil were provided with protective clothing and respiratory equipment to protect against inhalation ingestion and body contamination. Personnel were required to shower and change clothing at the end of each work shift and all workers were provided full radiation monitoring and dosimetry services as appropriate.

The primary control for possible resuspension of contamination was an 8' X 16 floorless metal building that was equipped with a door window high efficiency particulate air (HEPA) filter and r mover. This building isolated the immediate digging area, and was moved as required.

A plywood walkway was installed between the digging site and the adjacent roadway to provide access to the contaminated area. The walkway was used for personnel and equipment access and for removal of soil from the area. It was periodically checked for any spread of contamination

Dust palliatives such as water and/or soil stabilizer spray were used periodically to control resuspension of soil during and after the operation

A portable low-volume air sampler (2 cfm) was located inside the building, and portable high-volume (40 cfm) samplers were run outside the building at probable downwind locations. Operations were halted if persistent wind speeds over 24 km/hr (15 mph) were measured

Contaminated soil was hand-excavated from one small area at a time and placed in plastic bags.

ie bags were monitored before being removed on the environmental protection building. The bags were then placed in plastic lined 4 × 4 × 7'

boxes for shipment offsite. Next the excavated area was resurveyed with a FIDLER. This entire process was continued until contamination levels were below the detectability limit of the FIDLER (~250 counts per minute in the lip area). Each excavated area was covered with clean top soil and reseeded with native grasses

The 1976 soil removal operation was terminated on September 9 1976. A total of 35 boxes weighing approximately 125 000 lb had been removed and shipped offsite at an approximate cost of \$44 000. There were no personnel exposures and air sampling data indicated there was no adverse environmental impact. Figure 3 shows annual average plutonium concentrations for the three routine high-volume (40 cfm) ambient air samplers located in the areas most likely to be influenced by any resuspension of contamination from the 903 Lip Area.

SOIL REMOVAL PROJECT - SUMMER 1978

Reviews conducted after completion of the 1976 soil removal project indicated that while the tech nique used was safe it was inefficient when comparing time consumed versus the large amount of contaminated soil still requiring removal from the 903 Lip Area.

New techniques for soil removal with mechanized equipment were developed and meetings to discuss the new techniques were held with Colorado Department of Health (CDH) personnel. Practice sessions using the new techniques were performed for DOE and CDH observers during the summer of 1977

In April 1978 a Rocky Flats Operational Safety Analysis was written for contaminated soil removal using these techniques. Soil removal in the 903 Lip Area using the new techniques, began on June 27 1978. The procedure involved use of a front end loader alone or in conjunction with a road maintainer and/or dozer. Hand digging was done in any area where mechanized equipment could not be used.

4




FIGURE 3 Annual Average Plutonium Concentrations in 1976 for Ambient Air Samplers Located Near 903 Lip Area During Soil Removal

Prior to starting soil removal the area to be excavated was premoistened by a sprinkler system for three days. A moisture content of approximately 15% was required Water was available at all times for sprinkling on an as required basis.

Personnel restrictions regarding protective clothing and respiratory equipment remained the same as those used for the hand digging method. At least three portable high-volume ambient air samplers were operated at all times that work was in progress.

A Rocky Flats Environmental Sciences representive was in the 903 Lip Area during all perations with authority to terminate the work if any of the following events occurred

- 1 Wind speeds in excess of 24 km/hr (15 mph)
- 2. Any visible dust, or any indication that area sprinkling was inadequate
- 3 Total long-lived alpha concentrations greater than 0 06 pCl/m³ as measured on filters from the portable ambient air samplers.

All contaminated soil was loaded into plastic-lined 2' X 4' X 7' plywood boxes for offsite shipment. All boxes were sealed nailed and transported to locked fenced storage and were steel-banded before the end of each work day. The boxes subsequently were shipped by truck to the Nevada Test Site for storage.

RFP 3226

Il soil in the 903 Lip Area that exceeded 2000 counts per minute as determined by a FIDLER was removed. Cleaned areas were resurveyed and soil removal was continued until background (approximately 250 counts per minute by FIDLER for these particular areas) readings were obtained

Contaminated soil removal from the 903 Lip Area was completed on October 13 1978 Topsoil was applied to the entire excavated area and the area was reseeded with native grasses

During the 1978 phase of this project a total of 1448 boxes weighing approximately 4.7 million pounds were removed and shipped offsite at an approximate cost of \$410,000. There were no personnel exposures and air sampling data indicated no adverse environmental impact. Table 1 shows total long lived alpha data from the portable ambient air samplers. Samplers 1.3 were operated only during periods when excavation was taking place. Sampler 4 operated continuously. If after 48 hr. a sampler exceeded the action level of 0.02.

TABLE 1 Total Long Lived Alpha Concentrations From Portable Air Samplers During Lip Area Soil Removal (June 27-October 13 1978)

	Sampler No 1		Sampler No. 2		Sampler No. 3		Sampler No. 4	
Date	48-hr Count (pCl/m)	72-hr Count (pCVm²)	48-hr Count (pCi/m)	72-hr Count (pCI/m²)	48-kr Count (pCl/m³)	72-hr Count (pCl/m²)	48-hr Count (pCI/m)	72-hr Count (pCi/m)
6 28 78	0.627	0.033	1.017	0.034	0.092	0.027	< 0.001	-
6 30-78	< 0 001	-	< 0.001	-	0.008	-	< 0.001	_
7-05 78	< 0 001		0.106	0.023	< 0.001	_	0.055	0 022
7-06 78	0.095	0.109	0.188	0 130*	< 0.001	_	0 021	0 009
7-07 78	0.029	0.037	< 0.001	_	0.029	0 034	< 0 001	-
7 10-78	0 1 1 6	< 0.001	0.174	0.038	< 0.001	-	< 0.001	-
7 11 78	-	-	-	-	_	_	0.046	< 0 001
7 12 78	-	_	_	_	_	-	< 0.001	_
7 13-78	< 0 001	_	_	-	-		0.019	0 002
7 14 78	< 0 001	_	< 0.001	_	< 0.001	-	< 0 001	_
7 17 78	_	_	-	-	-	-	< 0.001	-
7 18-78	-	-	-		_	_	0.046	< 0 001
7 19-78	0 138	0.019	0.545	0.795	0.079	0.022	< 0.001	_
7 20-78	0.031	0 026	-	-	0.020	0.027	0 019	0 014
7 21 78	< 0.001	-	0.008	_	800.0	-	0.003	**
7 24-78	0.088	0.046	< 0.001	-	0.029	0.014	0.004	-
7 25-78	-	-	-	-	•	-	0.005	_
7 26-78	< 0.001	-	< 0.001	_	0.004	-	< 0.001	-
7 27 78	_	_	-	-	-	_	< 0.001	_
7 31 78	0.021	< 0.001	< 0.001	_	< 0.001	-	-	
8-01 78	0.067	0.038	< 0.001	_	< 0.001	-	_	_
8-02-78	0 064	0.002	< 0.001	_	< 0.001	_	0.005	-
8-03-78	_	_	-		-	-	0.045	0.013
8-04-78	-	-	_	_		-	0.006	_
8-07-78	< 0.001	-	< 0.001	_	0.159	0.035	0.003	_
6-08-78	0.335	< 0.001	0.239	0.019	0.001	-	0.031	< 0 001
8-09-78	< 0.001	-	0.002		< 0.001	_	0.007	-
8-10-78	-	-	_	-	-	_	0.004	-
8-11 78	< 0.001	_	0.018	< 0.001	0.045	0.007	< 0.001	-
8-14-78	-	_	-	-	-	_	0.008	_
8-LS-78	-	_	_	_	_	_	< 0.001	_
8-16-78	0 216	0.218*	0.028	0.018	0.028	0.041	0.061	1000>
8-17 78	0.031	< 0.001	< 0.001	_	< 0.001	-	0.007	-
8-18-78		_	-	-	-	-	0.014	0.018
J-21 78	-	-	-	-	-	_	0.023	0.068

Exceeds automatic shutdown level of 0.06 pCl/m (72-hz count).

continued

TABLE 1 (Concluded)

	Sampler No 1		Sampler No 2		Sampler No 3		Sampler No. 4	
D te	48-hr Count (pCl/m)	72-hr Coynt (pCI/m)	48-hr Count (pCl/m)	72-hr Count (pCI/m)	48-hr Count (pCt/m)	72-hr Count (pCi/m)	48-hr Count (pCi/m)	72-hr Count (pCI/m)
8-22 78	0 338	0 254	0.045	< 0 001	0 039	< 0 001	0 034	0 049
8-23 78	0 402	0 09	< 0 001	-	0 046	0 04	< 0.001	000,
8-24-78	0 195	0 096	< 0.001	-	< 0 001		< 0.001	-
8-25 78		-	-	_	-	-	-	-
8-28-78	0 085	0 036	< 0.001	_	0 036	< 0.001	0 028	0.006
8-29-78	< 0.001		< 0.001	_	< 0.001		0 064	0.006
		_		< 0.001				
8-30-78	< 0 001	-	0.067		0 039	< 0 001	0 088	< 0 001
8-31 78	< 0 001	-	< 0 001	-	800 0	-	0.024	< 0 001
9-01 78	-	-	_	-	-	-	0 007	-
9-05-78	< 0 001	-	< 0 001	-	< 0 001	-	0.008	-
9-06-78	0 208	0 063	< 0.001	-	< 0 001	-	0.078	0.013
9-07 78	-	-	-	-	-	-	0.007	_
9-08-78	-	-	-	-	-	-	< 0.001	_
9-11 78	-	-	-	-	-	_	< 0.001	-
9-12 78	< 0 001	_	< 0.001	-	0 103	0 019	0.041	0 004
9-13-78	< 0.001	_	< 0.001	-	< 0 001	-	0.075	0 014
9-14 78	-		-		_	_	0 047	0.001
9-15-78	_	_	-	-	-	-	0.618	< 0.001
9-18-78	_	_	-	-	_	-	< 0.001	-
9-19-78	_	-	-		-	-	< 0 001	-
9-20-78	_	-	-	-		-	< 0 001	-
9-21 78	0 077	0.007	0.026	< 0.001	0 037	< 0.001	< 0.001	-
9-22 78	-	-	-	-	_	_	< 0.001	-
9-25-78	_	-	_	_	_	-	< 0.001	-
9-26-78	0 005	-	< 0.001	-	0.002	_	< 0.001	-
9-27 78	< 0.001	-	< 0.001	_	< 0.001	-	< 0.001	_
10-03-78	0 232	0.007	< 0.001	_	< 0.001	-	0.053	0.007
10-04-78	-	-	_	_	_	_	< 0.001	_
10-05-78	_	_	_	_	_	_	< 0.001	_
10-06-78	100.0	_	0.027	0 003	< 0.001	~	0.007	_
10-09-78		_	-	-	~ 0.001	_	0.007	_
10-10-78	0 038	0.004	< 0.001		< 0.001		-	_
10-10-78			< V.VV.		< 0.001	-	< 0.001	-
10-12 78	-	-	-	_	-	-	0.002	-
	-	-		-	- - 0.001	-	4.002	-
10-13-78	0 005	-	< 0.001	-	< 0.001	-	-	-

Exceeds automatic shutdown level of 0.06 pCl/m² (72-he count).

pCi/m³ another measurement would be made after 72 hr A 72-hr measurement of > 0 06 pCi/m³ resulted in an automatic shutdown of activity

Table 2 shows the monthly average plutonium concentrations for the three routine high volume ambient air samplers located in the areas most likely to be influenced by any resuspension of contamination from the soil removal project. Concentrations t these samplers remained within ranges normally expected considering the effects of two atmospheric nuclear weapons tests conducted by the

Peoples Republic of China during the same time period.

Table 3 shows annual average plutonium concentrations for the same three ambient air samplers over a five-year period

CONCLUSIONS

Approximately 0.5 curie of plutonium was removed from the 903 Lip Area through extensive soil removal activities conducted during the summers of

A SAME AND ADDRESS OF THE PARTY OF THE PARTY

TABLE 2 Monthly Average Plutonium Concentrations for Ambient Air Samplers Located Near 903 Lip Area Soil Removal

	Sampler 7	Sampler 8	Sampler 9
1978	(pCi/m)	(pCi/m)	(pCv/m)
Janu ry	0 00021	0 00261	0 001 10
February	0 00013	0.00020	0 00030
March	0 00018	0 00022	0 00044
April	0.00054	0 00077	0 001 29
May	0.00015	0 00025	0 00029
June	0 00014	0 00004	0 00031
July	0.00024	0 00045	0 00096
August	0 00042	0 00049	0 00087
September	0 00039	0 00054	0 00061
October	0 00026	0.00060	0 00090
No ember	0.00012	0 00068	0 00123
December	0.00033	0 00177	0 00164

NOTE The Radioactivity Concentration Guide (RCG) for soluble plutonium in ambient air accessible to incidentally exposed individuals is 0 06 pCl/m³

1976 and 1978 This quantity is based on an average concentration of 1200 d/m/g of plutonium ontamination in soil and a density of 1 g/cm³

Two completely different methods of removing contaminated soil were implemented during this extensive cleanup project. Both methods proved to be safe for personnel involved in the project and both methods were employed with no adverse

TABLE 3 Annual A erages of Plutonium Concentrations for Ambient Air Samplers Located Near 903 Lip Area

Yea	Sampler 7 (pC/m)	S mpler & (pCt/m)	Sampler 9 (pCt/m)
1974	0 00084	0 00317	0 00051
1975	0 00057	0 00046	0 00049
1976	0 00054	0 00053	0 00135
1977	0 00024	0 00053	0 00059
1978	0 00028	0 00069	0 00086


NOTE The Rad cit ity Concentration Guide (RCG) for solible ple tonium in ambient air accessible to incidentally exposed individuals is 0.06 pCVm⁸

environmental impact. The technique used during the summer of 1976 proved to be inefficient however. An entire summer of hand digging in a floorless building yielded a total of 35 boxes of contaminated soil, which were removed at an approximate cost of \$44,000 or \$1,257,14 per box. Use of mechanized equipment during the summer of 1978 yielded a total of 1,448 boxes of contaminated soil. These boxes were removed at an approximate cost of \$410,000 or \$283,15 per box.

Future soil removal projects at the Rocky Flats
Plant will incorporate the use of mechanized equipment with hand digging implemented only for isolated small areas or in areas where the use of mechanized equipment is not feasible

Harris and the second s

OVAL OR PLUTONIUM CONTAMINATED SOLL FROM



This report was prepared an account of work sponsored by an agency of the United States Government. Neither the United States Go ernment nor any agency thereof nor any of the employees makes any warranty express or implied or assumes any legal liability or responsibility for the accuracy completed bear, or usefulness of any information apparatus, product or improcess disclosed for represents that its use would not infringe privitely owned lights. Reference herein to any specific comfinerial product process or service by trade name trademark, mainfactured for otherwise does not necessarily constitute or imply its endottement recommendation of a sworing by the United States of the United States Government or any agency thereof. The reversal population of the United States Government or any agency thereof.

Printed his the United States of America Available from the National Technical Information Service

U.S Department of Commerce Springfield, Virgina 22161

Page Range Domestic Price*

001-025 - \$6.00

026-050 - 7.50 - 9.0